

Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 7




Fig. 5

POSSIBLE MALFUNCTION IN DUPLEXING UNIT.  
PLEASE CLICK "OK" TO PRINT TWO-SIDED TEST PAGE.

**OK**

Fig. 6

DID THE TEST PAGE PRINT PROPERLY?

**Yes** **No**

05918688.073001  
T00E20 8898T650